

3F, Building Block 2, No. 3400 Gonghexin Road,  
Jing'an District - Shanghai 200436, P.R. CHINA  
上海市静安区共和新路3400号2幢3层  
Tél. : +86 21 68 55 50 32  
Fax : +86 21 68 55 50 33  
E-mail : [ctcshanghai@ctcgroupe.com](mailto:ctcshanghai@ctcgroupe.com)

Report No.: S210100450\_1

21 January 2021

june.guo@pipchinaltd.com

**APPLICANT:** PROTECTIVE INDUSTRIAL PRODUCTS HONG KONG LTD., (C06226)

FLAT 1-11,  
6/F KAR WAH INDUSTRIAL BUILDING  
8 LEUNG YIP STREET  
. YUEN LONG, N. T  
HONG KONG

Date of receipt : 18 Jan. 2021

Testing period : 21 Jan. 2021

: 21 Jan. 2021

**Buyer:** ---

**Sample description:** Disposabel Nitrile Glove

Style / Article no. : 63-230PF

Test(s) requested : ---

Service : REGULAR

Brand / Section : ---

Season : ---

End use : ---

Factory name : ---

Factory code : ---

**For CE Marking : Yes**

Previous report : ---

Product category : ---

Product type : ---

Test stage : FIRST TEST

Supplier name : ---

Exported to : ---

## 1. Conclusion:

	Tests description	Conformity
1	Detection of Silicone	None

Pass: requirements met    Fail: requirements not met    None: no requirement for this test    N/A: not applicable

Approved by



Yvonne MAO 茅璇怡

Senior Analytical Chemical Engineer

Report No.: S210100450\_1

21 January 2021

APPLICANT: PROTECTIVE INDUSTRIAL PRODUCTS HONG KONG LTD., (C06226)

**2. Sample(s) description assigned by laboratory:**

<u>Size</u>	<u>Analyzed product</u>	<u>Description</u>	<u>Sample information</u>
	GLOVE	palm	



210100450



Report No.: S210100450\_1

21 January 2021

APPLICANT: PROTECTIVE INDUSTRIAL PRODUCTS HONG  
KONG LTD., (C06226)

### 3. GLOVE/

palm

	Method	Client Requirement	Unit	Result	Conformity
<ul style="list-style-type: none"> <li>● <b>Detection of Silicone</b></li> </ul> Detection of Silicone	CTC in house			Absence	

### END OF TEST REPORT

- : The test was carried out by external accredited laboratory, not within their accreditation scope.

